




Picture 1 & 2 : Loading of 3 metallic pallets:



Pictures 3, 4 & 5 : stowing the metallic pallets with belts

- 2 belts for each row of 3 pallets



Picture 5 & 6 : maintaining bars and "goulotte" with regupol

