



| | | | |
|---|----|------------|-----------------------|
| 8 | K5 | D=200-0,1, | $\varnothing=160+0,1$ |
| 8 | K5 | D=250-0,1, | $\varnothing=200+0,1$ |
| 2 | K5 | D=250-0,1, | $\varnothing=160+0,1$ |
| 4 | K5 | D=125-0,1, | $\varnothing=110+0,1$ |
| 8 | K5 | D=160-0,1, | $\varnothing=125+0,1$ |

$t = 11 \text{ mm}$

Okvádové hrany průměrnů srazit z obou stran 0,5x45°