

## BubaV- seznam vodičů - slaboproud

Označení vodiče	Odkud	Kam	Typ vodiče	pozn.
WS 001	R1	RACK	2x FTP Cat.6	
WS 002	R1	SolarMonitoring	2x FTP Cat.6	
WS 003	R1	KEY.1	SYKFY 3x2x0,5	
WS 004	R1	DK.1	SYKFY 3x2x0,5	
WS 005	R1	DK.2	SYKFY 3x2x0,5	
WS 006	R1	DP90.1	SYKFY 3x2x0,5	
WS 007	R1	DP90.2	SYKFY 3x2x0,5	
WS 008	R1	DP90.3	SYKFY 3x2x0,5	
WS 009	R1	DP90.4	SYKFY 3x2x0,5	
WS 010	R1	DP90.5	SYKFY 3x2x0,5	
WS 011	R1	MG.6	SYKFY 2x2x0,5	
WS 012	R1	SIR.1	SYKFY 3x2x0,5	
WS 013	R1	ZČ.1	SYKFY 3x2x0,5	
WS 014	R1	ZČ.2	SYKFY 3x2x0,5	
WS 015	R1	ZČ.3	SYKFY 3x2x0,5	
WS 016	R1	CRI.1	J-Y(St)Y 2x2x0,8	
WS 017	R1	Rekuperace.1	J-Y(St)Y 2x2x0,8	
WS 018	RACK	WIFI.1	FTP Cat.6	
WS 019	RACK	ETH.1	2x FTP Cat.6	
WS 020	RACK	ETH.2	2x FTP Cat.6	
WS 021	RACK	ETH.3	2x FTP Cat.6	
WS 022	RACK	ETH.4	2x FTP Cat.6	
WS 023	RACK	ETH.5	2x FTP Cat.6	
WS 024	RACK	ETH.6	2x FTP Cat.6	
WS 025	RACK	ETH.7	2x FTP Cat.6	
WS 026	RACK	GIOM 3000	FTP Cat.6	
WS 027	R1	tepelné čerpadlo.1	FTP Cat.6	
WS 028	RACK	STA	4x koax Kh21d	
WS 029	RACK	TV.1	koax Kh21d	
WS 030	RACK	TV.2	koax Kh21d	
WS 031	RACK	TV.3	koax Kh21d	
WS 032	RACK	TV.4	koax Kh21d	
WS 033	RACK	TV.5	koax Kh21d	
WS 034	R1	TC.1 - TC.10	smyčka J-Y(St)Y 2x2x0,8	
WS 035	R1	V.5	J-Y(St)Y 2x2x0,8	
WS 036	R1	T.1	J-Y(St)Y 2x2x0,8	1
WS 040	R1	T.5	J-Y(St)Y 2x2x0,8	1
WS 041	R1	T.6	J-Y(St)Y 2x2x0,8	propoj do Vrata.1
WS 047	R1	T.12	J-Y(St)Y 2x2x0,8	1
WS 048	R1	T.13	J-Y(St)Y 2x2x0,8	1
WS 049	R1	T.14	J-Y(St)Y 2x2x0,8	1
WS 051	R1	T.16	J-Y(St)Y 2x2x0,8	1
WS 053	RACK	V.1	FTP Cat.6	videovratny_vnejsi_jednotka
WS 054	RACK	V.1b	FTP Cat.6	videovratny_vnitrni_jednotka
WS 055	R1	KEY.2	SYKFY 3x2x0,5	
WS 056	R1	R -bazen date	FTP Cat.6 + Jysty 2x2x0,8	